



IPMS Silverwings Sacramento

Sacramento Modelers Club

A local modeling club affiliated with the International Plastic Model Society/USA URL: <http://www.sacramento-model-club.org>

ARTHUR R. SILEN, *CHAPTER PRESIDENT*

Making Open Face Resin Castings — Checklist

- Silicone rubber moldmaking material.
- Casting resin and hardener.
- Measuring spoons / cups.
- Hardened plate glass, 4 × 6, beveled edges and corners, for flattening pour holes.
- Mold release spray or brush on liquid.
- Talcum powder or baby powder for breaking surface tension within pour molds between casting resin and mold surface.
- Single edged razor blade for separating shallow surface molded resin from glass plates.
- Uninsulated brass wire for butt-joining resin castings together using cyanoacrylate glue.